

(Old) Digital Speed Indicator Calibration Chart – Without MPH/Distance Key

Use this procedure to calibrate older herbicide units without a MPH/Distance Key.

For Older Units Without a <i>MPH/DIST</i> Key	
STEP	ACTION
1	Clear <i>Field Acres</i> by pressing and holding key for approximately 3 seconds, then release when readout displays <i>0.0</i> .
2	Clear <i>Total Acres</i> by pressing and holding key for approximately 3 seconds, then release when readout displays <i>0.0</i> .
3	Press and hold W (Width) key and at the same time, press the "+ or -" key the change digital readout to display <i>99</i> , then release.
4	Press and hold C (Circumference) key and at the same time, press the "+ or -" key to change circumference readout to display <i>5.0</i> , then release.
5	Clear <i>Total Acres</i> by pressing and holding key for approximately 3 seconds, then release when readout displays <i>0.0</i> .
6	Drive the vehicle for a distance of <i>exactly one-mile (5,280 feet)</i> , then safely stop (the speed sensor will likely display a value between <i>0.4</i> or <i>0.6</i> Total Acres).
7	Press and hold the <i>Total Acres</i> key and at the same time, press the "+ or -" key to change digital readout to display <i>1.0</i> , then release.
8	Press and release <i>C (Circumference)</i> key to read Circumference.
9	If the digital display reads " <i>Help Calib</i> ", return to Step 4 and repeat steps 4 through 8; Otherwise go to step 10.
10	Record the Circumference number on the front cover of the Herbicide Record Book.